COBOT TURN 100 A



230
48
24
10
350
350
< 70
0 – 90
endlos
20 – or according to diagram
90 – or according to diagram
100 – or according to diagram
998x486x506
200
240
550
750
not extending beyond the edge of the welding table





